

## Verification Inspection: For Existing Registered E-Scooters

LTA will schedule mandatory inspections for e-scooters registered before 1 April 2020 and were declared as compliant to the device criteria of no more than 20kg, 70cm and 25km/h device speed, as well as UL2272-certified. This first-time inspection will be at **no cost** to these owners. Owners of these devices will receive a notice from LTA informing them to bring their devices in for inspection at any of the nine E-scooter Inspection Centres (EICs) island-wide. Please refer to the [locations of the inspection centres \(PDF, 114kb\)](#).

Those who fail to send their devices for inspection by the deadline stated in the notice could have their devices deregistered and face a fine of up to \$1,000 and/or jailed up to three months, if convicted.

Please ensure that your e-scooter registration mark is affixed **at the front or at the sides of your e-scooter stem**, is **upright, intact, not obscured and not void/damaged** before presenting for inspection. E-scooters with missing/invalid registration mark will be barred from inspection. Owners who require a replacement of the registration mark for their e-scooter may wish to submit a request via [www.lta.gov.sg/feedback](http://www.lta.gov.sg/feedback) with more details<sup>1</sup> and schedule an appointment with LTA for the registration mark. Do note that a fee of \$20.00 for the replacement of the registration mark will be chargeable, and the registration number of the e-scooter will be changed.

Owners who require more time to present their e-scooter(s) for inspection may wish to write in to [LTA\\_escooter\\_insp@lta.gov.sg](mailto:LTA_escooter_insp@lta.gov.sg) with more details.

E-scooters that do not pass the mandatory inspection due to non-compliance with the weight, width, speed or UL2272 certification requirement will be deregistered by LTA. Owners who wish to request for a re-inspection of their e-scooter(s) may write in to [LTA\\_escooter\\_insp@lta.gov.sg](mailto:LTA_escooter_insp@lta.gov.sg) after completing the necessary adjustments to ensure compliance with LTA's device requirements.

<sup>1</sup> *If your registration mark is damaged, please provide a photograph of the damaged registration mark to LTA for assessment, the registered owner's full name and the last 4 characters of the Singapore NRIC/Employment Immigration Pass Card (e.g. 321A).*

*If your registration mark is missing, please make a police report on the loss of your registration mark first, followed by providing LTA with the e-scooter registration number, the registered owner's full name and the last 4 characters of the Singapore NRIC/Employment Immigration Pass Card (e.g. 321A).*