

Location of Crack on Bogie Frame




Photo of Bogie Frame Cracks

